Dell Precision 5510 Battery Replacement

This guide will show how to replace the battery component of the Dell Precision 5510 laptop.

Written By: Atlanta Phelps

This document was generated on 2020-11-28 06:53:16 AM (MST).

INTRODUCTION

These are the steps to remove the battery from the Precision Dell 5510.

TOOLS:

- Phillips #0 Screwdriver (1)
- JIS #0 Screwdriver (1)

PARTS:

- Dell XPS 15 9550 and 5510 Precision 84 Wh Replacement Battery (1)
- Dell XPS 15 9550 and 5510 Precision 56 Wh Replacement Battery (1)

This document was generated on 2020-11-28 06:53:16 AM (MST).

Step 1 — Base Cover

- Open the system badge flap over to reveal the screws underneath (marked 1 on the image).

- Remove the 12 screws that secure the base cover to the computer.

Step 2

- Pry the edges base cover and lift it to remove it from computer.

This document was generated on 2020-11-28 06:53:16 AM (MST).

Step 3 — Battery



- Unplug the connection that links the battery to the computer.

Step 4

- Remove the four 4.0 mm JIS #0 screws surrounding the battery.

This document was generated on 2020-11-28 06:53:16 AM (MST).

Step 5

- Carefully remove the battery from the computer.

To reassemble your device, follow these instructions in reverse order.