HP Pavilion 15-cc023cl Optical Drive Replacement

Replace the Optical Drive.

Written By: Stephanie Henry

INTRODUCTION

Replacement of the Optical Drive for the HP-Pavilion 15-cc023cl.

TOOLS:

- Phillips #000 Screwdriver (1)

www.iFixit.com

Step 1 — Optical Drive

● Use a PH000 screwdriver to remove the 4mm screw that secures the optical drive.

Step 2

● Take optical drive out of the laptop

To reassemble your device, follow these instructions in reverse order.

This document was generated on 2020-11-28 06:59:44 AM (MST).