# Capresso Perfectea 260 Motherboard Replacement

Replace the motherboard with the Capresso Prefectea 260.

Written By: Rohin Chander

INTRODUCTION

This guide will teach you how to replace the motherboard within the Capresso Perfectea.

🔧 TOOLS:

- [Phillips #2 Screwdriver](#) (1)
- [Metal Spudger](#) (1)

www.iFixit.com

Step 1 — Motherboard

- First, take the base of the device and flip it over.

Step 2

- Remove the four 12 mm Phillips #2 screws surrounding the base then lift the bottom half of the base to expose the circuit boards inside the device.

Step 3

- Remove the two 7.5 mm Phillips #2 screws holding in the motherboard

Step 4

- Unplug the wire going into the side of the motherboard

Step 5

- Use the metal spudger to cut open the rubber covering the latch where it clamps onto the copper tab.

- Unplug wire at heating element by first using the metal spudger to push the latch in and then pushing it out.

- ⚠ Be careful when unplugging the wire as if it is done too forcefully it can damage the connection and make it difficult to connect a new motherboard

Step 6

- Lift the motherboard out of the device

To reassemble your device, follow these instructions in reverse order.