PlayStation VR Processor Unit Cooling Fan Replacement

A damaged or broken cooling fan can make your...

Written By: Sarah Shand

INTRODUCTION

A damaged or broken cooling fan can make your system overheat so it is important to replace it if that happens in order to prevent any further damage to the system.

🔧 TOOLS:

- iFixit Opening Tool (1)
- Phillips #000 Screwdriver (1)
- Tweezers (1)

Step 1 — Processor Unit Cooling Fan

- On one side of the console (the side adjacent to the fan vent), there will be two 6 mm screws. Unscrew them with a PH #000 screwdriver.

Step 2

- Press and slide the side panel (it will have the two ports) back to reveal an additional 6 mm screw.

- Unscrew the 6mm screw with a PH #000 screwdriver.

Step 3

- Slide the panel back into place.

Step 4

- Using a plastic opening tool, carefully pry the panel from the main console to reveal the HDMI ports.

- ⓘ You will probably need to lift it on both sides in order for the panel to come loose.

This document was generated on 2023-02-07 05:40:14 PM (MST).

Step 5

- Turn the console over.

- Unscrew the two 9 mm screws with a PH #000 screwdriver.

Step 6

- With the plastic opening tool, carefully pry the console shell panel free and lift it away.

This document was generated on 2023-02-07 05:40:14 PM (MST).

Step 7

- Using tweezers, carefully pull the multi colored bundled cable from its port connecting the fan to the console.

- Carefully lift the fan and its wiring from the device.

- ⓘ Be mindful of damaging the wires.

- ⚠ Take care to keep your fingers away from the fan blades.

To reassemble your device, follow these instructions in reverse order.

This document was generated on 2023-02-07 05:40:14 PM (MST).