




Samsung Galaxy Tab A 9.7 Headphone Jack Replacement

This guide provides step by step instructions on how to replace the headphone jack on your Samsung Galaxy Tab A 9.7

Written By: Justin Osborn



This document was generated on 2020-11-28 07:25:10 AM (MST).

INTRODUCTION

This replacement guide will help you easily follow the steps in order to replace the headphone jack on a Samsung Galaxy Tab A 9.7. The difficulty of this guide is moderate and requires special attention to details.

The headphone jack is also a part of the charging port, so for clarification the part listed is both the charging port connected with the headphone jack.

TOOLS:

- [iFixit Opening Tools](#) (1)
- [Phillips #000 Screwdriver](#) (1)
- [Magnetic Project Mat](#) (1)

PARTS:

- [Samsung Galaxy Tab A 9.7 Charging Assembly](#) (1)

Step 1 — Headphone Jack



- Pry along the edge of the Samsung Galaxy Tab A 9.7 with an iFixit opening tool.

Step 2




- Insert a second iFixit opening tool along the edge and begin to pry open the back cover a little with each one.

Step 3





- Remove one of the opening tools and begin to go around the device with the other one until the back cover pops off.

Step 4





- Disconnect the strip from the motherboard with the iFixit opening tool.

Step 5




- Remove five 2.8 mm screws using the Phillips #000 screwdriver.

Step 6



- Remove both side pieces using one of the the iFixit opening tools.
- Lift up the headphone jack port with the iFixit opening tool as well.

Step 7



- Pull up the headphone jack port carefully and replace.

To reassemble your device, follow the instructions in reverse order.