



Replacing Coffee Spout Manifold on Melitta Caffeo Solo

When the Coffee Spout Manifold is clogged with...

Written By: VauWeh



INTRODUCTION

When the Coffee Spout Manifold is clogged with f. E. coffee fat, then the coffee only comes out in spurts, often out of only one of the two jets. The Spout Manifold is a sealed-off compartment with venting valves, which doesn't open and is hard to clean. The replacement part doesn't cost much and the replacement is fairly easy.



TOOLS:

- [New Item](#) (1)



PARTS:

- [Coffee outlet distributor Melitta](#) (1)

Step 1 — Coffee Spout Manifold



- ❗ The glossy cover over the coffee spout is only snapped into place.
 - At the cover bottom you will find a tab in the middle above a catch. Lift the tab a little with a flat screwdriver and detach it from the catch.
 - Lift up the cover.

Step 2



- The coffee spout distributor is only snapped into place. Use your fingers to grab it from the top and lift it away from the machine. The first time it may stick pretty tight.

Step 3



- Remove the chrome trim from the outlet nozzles.
- Slide off the inlet hose.

Repeat the steps in reverse order to reassemble the device.