



Acer Aspire 5750Z-4566 Hard Drive Replacement

How to replace the hard drive of my Acer Aspire 5750Z-4566.

Written By: Okeoghene Agbahowe



INTRODUCTION

If your Acer Aspire (model 5750Z-4566) is displaying the error message; Smart failure predicted on the hard drive. Use this guide to replace the hard drive (also known as a hard disk).

The goal of this guide is to show the steps involved in the replacement of an Acer Aspire 5750Z-4566 hard drive. A hard drive failure may occur in the course of a normal operation or due to an external factor such as exposure to water or environmental contamination, which can lead to a crash.

This guide is necessary because hard drive failure often leads to data loss. It is essential to replace the hard drive when the computer experiences signs of a hard drive failure. It enables one the opportunity to back up the data stored on it and replace it before it completely wears out. The only tool required will be a Philips #0 screwdriver.



TOOLS:


- [Phillips #0 Screwdriver](#) (1)
-

Step 1 — Hard Drive




- ❗ Power off your laptop before beginning disassembly.
- Flip the laptop over.

Step 2



- Place a screwdriver or a pen in the orange tab, then slide it to the right.

Step 3




- Slide the battery out and remove it.

Step 4




- Remove the two M2.5X8 screws using the Phillips #0 screwdriver.

Step 5



- Remove the cover to access the hard drive.

Step 6



- Pull the tab and lift up to remove the hard drive.

To reassemble your device, follow these instructions in reverse order.