


iMac Intel 21.5" Retina 4K Display Fan Replacement

Prerequisite for removing fan after the hard drive brackets.

Written By: Evan Noronha



INTRODUCTION


Prerequisite only.

TOOLS:


• T10 Torx Screwdriver (1)

Guide ID: 64113 - Draft: 2020-01-07

Step 1 — Fan




• Gently pull the fan cable connector straight out of its socket on the logic board.



Step 2

- Remove the three 10 mm T10 Torx screws securing the fan to the rear enclosure.
- (i) The uppermost screw has a rubber standoff adhered to its head to support the display—leave this in place.

Step 3



• Remove the fan from the iMac.

To reassemble your device, follow these instructions in reverse order.