



1999-2004 Honda Odyssey EGR Port Cleaning

A video tutorial on how to clean the EGR port on a 1999-2004 Honda Odyssey. Also helps if you are reading a code of P0401.

Written By: eCuration



INTRODUCTION

The EGR valve on the 1999-2004 Honda Odyssey is notorious for becoming clogged. If you are getting a P0401 code and or odd running issues then follow this guide to clean the valve.



TOOLS:

- [3/8" Drive Ratchet](#) (1)
- [10" Ratchet Extension](#) (1)
- [10mm Socket](#) (1)
- [10mm Wrench](#) (1)
- [Pick Tool](#) (1)
- [Throttle Body and Air-Intake Cleaner \(Carb\)](#) (1)
- [12mm Socket](#) (1)



PARTS:

- [Intake Gasket](#) (1)

To reassemble your device, follow these instructions in reverse order.